
play and recreation surfaces **EVERPLAY** INSTALLATION INC.

5 Year Extended Warranty for **EVERPLAY** Poured in Place Surface

This warranty extension is available for optional purchase and extends the regular 5 year warranty for the installed **EVERPLAY** poured in place surface to 10 years.

The conditions of the extension are:

- The warranty extension is purchased for a price of \$8.00/M2 or \$0.75/ft2 of the installed surface. The warranty extension may be purchased at the time of installation. The warranty extension may also be purchased at any time during the first 3 years after the installation of the **EVERPLAY** surface at a 15% increase and provided an ASTM F3313-19 test report is provided for a field test that is not older than 4 weeks prior to the date of extended warranty purchase.
- All **EVERPLAY** poured in place warranties require that the owner/operator must perform the maintenance as provided in the warranty document and available below and updated on the website, www.everplay.com.
- The owner/operator will arrange with **EVERPLAY** Installation Inc. for a surface inspection and drop test to ASTM F3313-19 in years 4, 6 and 8 at a cost of \$175.00 per play structure or clustered structures not exceeding a fall height of 1M, plus travel costs. The report will include the results of the testing and a report as to the state of the **EVERPLAY** surface and suggestions for maintenance or rejuvenation work that should be performed. Should there be a need to perform any work under the warranty; arrangements will be made with **EVERPLAY** Installation Inc. to have this work performed at no cost to the owner/operator.

The general terms of the warranty are:

The **EVERPLAY** "in situ" installed conforms to the formulations and standards **EVERPLAY** Installation Inc. This warranty is in lieu of any other warranties expressed or implied, including, but not limited to any implied warranty of merchantability or fitness for a particular use. To maintain the warranty in effect, the **EVERPLAY** maintenance procedures must be adhered to. Note that fading and wear of the pigment, painted, or EPDM surface are considered normal wear and tear. A split in the surface that does not allow for the free insertion of a Canadian or US quarter, is not a crack requiring repair. Not included is vandalism or other wilful acts.

The sole and exclusive remedy of the buyer against **EVERPLAY** Installation Inc. shall be for the replacement of the defective area for a period of five years from substantial completion. No other remedy, including, but not limited to, incidental or consequential damages for lost profits, lost sales, injury to person or property, or any other incidental, or consequential loss, shall be available to the buyer or owner. The polyurethane binders (SF138) utilized in the **EVERPLAY** "in situ" system and this project are the same as those formulated and manufactured for use in the **EVERPLAY** "in situ" system since 1990. The binders utilized in the **EVERPLAY** "in situ" contain no latex. Utilization of the SF138 will allow for the maintained **EVERPLAY** surface to remain resilient and perform within the requirements of the ASTM F1292-04, ASTM F1292-13, ASTM F1292-17 and ASTM F3313 for the warranty period when field tested with a Triax2010, Triax2015 or TriaxTouch instrument from the same drop heights and at the same locations tested at the time of the initial **EVERPLAY** installation and within the temperature range of -10°C and 50°C. The results of the drop tests at time of installation must provide a G-max less than 100 and HIC less than 850 for the noted drop heights when field tested with a Triax instrument. The warranty is to cover the performance that the surface continues to meet the requirements of CSA Z614-20 from the initial drop heights for the warranty period. For this warranty to be in effect, a report outlining the locations, drop height and results must be forwarded to **EVERPLAY** Installation Inc. within 60 days of the initial **EVERPLAY** installation.

play and recreation surfaces **EVERPLAY** INSTALLATION INC.

The current maintenance procedures are;

EVERPLAY "In Situ" MAINTENANCE PROCEDURES

EVERPLAY "in situ" is a poured in place recreation and play surface consisting of recycled rubber crumb bound together with a polyurethane binder. The thickness of the EVERPLAY "in situ" can range from 15mm (0.6") to 140mm (5.5") depending upon the application. The unique installation techniques that have been developed by EVERPLAY over the past 25 years allow for variation in resilience as required by the current standards. EVERPLAY "in situ" has been tested according to ASTM F3351 for both Head Injury Criteria (HIC) and Gmax. EVERPLAY "in situ" contains polyurethane binders throughout the entire thickness of the system that have been specifically formulated for this purpose.

Generally, the EVERPLAY will be kept clean with wind and rain, however there could be circumstances where mechanical cleaning may be required. Where the materials on the surface are larger than the pores in the EVERPLAY this would initially involve the sweeping of the surface with a broom. EVERPLAY sand, etc.) the particles are to be removed from the EVERPLAY with a vacuum or a leaf blower. Annually or as required the EVERPLAY should be vacuumed to remove any small particles that have been carried to the EVERPLAY. A utility vacuum or gas-powered landscape vacuum are to be utilized. There is a specialized pressure washer head available from Kracher and described in ASTM F2479 that can be used with the prior consent of EVERPLAY. Failure to perform this maintenance can lead to injury, damage or voiding the warranty.

Winter conditions can pose a hazard as a result of low temperatures, snow and ice. Should the EVERPLAY surface become covered with ice or snow, this can be removed with a plastic snow shovel. Where the ice or snow has penetrated the EVERPLAY, de-icing pellets can be used to melt the ice. Salt is not recommended, as the salt will damage the surrounding surfaces and/or the play structures. Removal of ice and snow will not improve resilience at low temperatures. During winter and at temperatures below -10° C or when not in a dry condition, the performance of the EVERPLAY will be compromised and it is recommended to discontinue use.

For further information on the EVERPLAY 5 year warranty extension, please contact your technical sales representative.

Yours truly,
EVERPLAY Installation Inc.



Per: Rolf Huber, President